www.MarutiMachinery.com

(THIS CERTIFICATE MUST BE HUNG UP IN THE BOILER HOUSE)

नं. नानिक्षेत्र | | 6113 1006 नाथक नियाम लोक्सोनी क्लेड

(Regulation 389)

1-8 JUL 2016

GUJARAT BOILER INSPECTION DEPARTMENT CERTIFICATE FOR THE USE OF A BOILER

Registry No. of Boiler:	Type of Boiler : Package
Boiler Rating: 274 M ² / 24	Place & Year of Manufacture : A.P. India- 2004
Maximum continuous evaporation :	
Name of Owner:	
S'triation of Boiler: www.N	MarutiMachinery.com
Repairs: 2009 : Boiler retrofit water wall as: 2015 : (1) 10 Nos. 2 nd pass smoke	sembly provided e tubes replaced (2) 25 Nos. membrane tubes replace
Remarks: <u>2009</u> : Boiler furnace controller w should be regularly monito	rith safety interlocks should be provided. Boiler water red.
Linda B. D. S.	16.0 Kg/6m ² I hereby certify that the above describ
	ked at a Maximum Pressures of 10.5 Kg/Cm ² for to cading of the each 63.5 mm Ø DPDSLSVs Safety val Front = 14.0 mm, Rear = 10.1 mm
nereby further certify that the main steam	m pipe was tested hydraulically to a pressure of
21:0 Kg/Cm ² last on 05. 05. 2004.	
ees Rs. 5000/- paid on 28.06.2016.	
Dated at	
his 5th day of July 2010	
1113 _3 uay 01 _July 2016.	
his <u>5th day of <u>July</u> 2016.</u>	
PEN UP BOILER FOR CLEANING AFTE	•
PEN UP BOILER FOR CLEANING AFTE	•
PEN UP BOILER FOR CLEANING AFTE	•
PPEN UP BOILER FOR CLEANING AFTER VERY FOUR WEEK AND KEEP RECOR	ZD.

ASST. DIRECTOR OF BOILER Deputy Director of Boiler CHIADAT CTATE WIRE

Cuisme Care a

Page 1 of 1